GSM-Support ul. Bitschana 2/38, 31-420 Krak·w, Poland
mobile +48 608107455, NIP PL9451852164 REGON: 120203925
www.gsm-support.eu

AsanSam Dongle

AsanSam Dongle is an ultimate phone flashing and mobile unlocking service solution for Qualcomm, Broadcom, Bada, DualSIM, Android, Infineon, Smart Phone, Swift and Trident based phones.

AsanSam Dongle Outstanding Features:

- Root/Unroot Android based Samsung cell phones
- Alphabetical phone model selection
- Automatic model selection with CPU information
- Info on required cables
- Fully customizable software assistant
- Automatic flash file selection for Qualcomm, Broadcom, Bada
- Informs user if phone must be connected with or without battery
- Read info from all Android based cell phones
- High speed Flashing
- Read/Write FULL FLASH for all Android based cell phones
- Super-fast USB flashing mode
- Safe and super-fast DualSIM, Swift flashing
- Repair all software errors
- Repair damaged NVM for all Android based cell phones
- Read/Write FULL NVM for all Android based cell phones
- Automatic login to the support area directly from the software
- Regular software updates
- Remove Pattern Lock with one click (need root)
- Reset User Code with one click (need root)
- Patch modem for Galaxy S, Galaxy S2

Supported models:

Qualcomm & Broadcom & Badawave:

A411, A412, A551, A561, A597, A637, A657, A697, A701, A706, A707 A711, A717, A727, A736, A737, A746, A747, A766, A767, A777, A801 A811, A817, A811, A821, A827, A836, A837, A867, A885, A886, A877 A887, A897,B3410W, B5310, B5310R, B5310U,C3510T, C5220 C5510 C5510H,C5510U, C6712,F330, F338, F400, F406, F408, F480, F480F F480G, F480H, F480R, F488, F490, F510, F550, F700,G400 G400F G400L G508, G508E, G800, G800B, G800L, G808,i6210 i6220 i6230,J200,200L,J208, J630, J638,L170, L400, L760 L760G, L768 L810, L811,M3710,M7500, M7600, M7600B M7600H, M7600L, M7603 M8800, M8800B M8800H M8800C, M8800L, M8800N, M8910, M8910B M8910H M8910U,P910, P920, P940, P950, P960,S3370 S3370B,S3370L, S3650, S3650C S3650H S3650M, S3650W, S3653 S3653M, S3653W S3853, S5230 S5230C, S5230G, S5230H S5230K, S5230M, S5230R, S5230W, S5233A S5233S, S5233T, S5233W, S5250 S5250W, S5253 S5333, S5350,S5350M, S5510, S5530, S5560 S5560 CS5560H, S5600, S5600B, S5600L S5603, S5603T S5608U S5620,S5620B S5628, S5628i, S7070 S7070C S7120H, S7120U S7220,S7330, S7350 S7350C, S7350E, S7350F, S7350H, S7350i S7520U S8000, S8000BS8000C, S8000H, S8000L S8000U,S8003 S8300 S8300C,S8300H S8300J,S8300N,S8300T,S8500,S8300J,S8300N S8300T,S8500,S8500C,T359, T469, T479, T559, T639 T659, T669 T746, T749, T819 T919,T929,U700,U700B,U708,U800,U800F,U808 U900,U708,U800,U800F,U808,U900, U900F, U900G, U900K,

U900U U900W, U908,V705, V706, V707, V708, V820L,Z150, Z170, Z230 Z238, Z240, Z240E, Z248, Z310, Z360, Z368, Z400, Z540 Z548, Z560, Z570, Z720, Z728, Z740, ZV40, ZV50, ZV60,... (All new bada and broadcomm phone)

Android:

B7510,I5500,I5510,I5700,I5800,I6500,I7500,I9000 Family I9001,I9003,I9010,I9020,I9023,I9100,S5570,S5660,S5 670 S5830,P1000,P1010,P7100,P7300,P7310,P6200,P6210,P7 500 P7510,N7000 All Android AT&T All Android T-Mobile All Android Sprint All Android Verizon

Swift & DualSIM:

A117, A137, A177, A226, A227, A237, A257, A256 B100i, B110, B110L, B130, B130L, B130S, B130T B210, B270i, B2100, B2700, B2703, B2710, B3410 B5702, B5712-C, B5722, B5722C, BC01,C145, C160 C160B, C160G, C160L, C160M, C161, C165, C166 C168, C168B, C180, C270, C276, C276L, C288 C3212, C3212i, C3300D, C3300K, C3303, C3303i C3303K, C3310C, C3322, C3500, C3510, C3518 C3610C, C3630C, C3730C, S3930C, C420, C420L C421, C425, C426, C450, C458, C5010B, C5110 C5130, C5130s, C5130U, C5212, C6112, C6112C CC01-i CC03, D500, D500E, D508, D510, D600 D600E, D606, D608, D618, D780, D788, D820 D828, D828E, D880, D888, D900, D900E, D900i D908, D908i, D980, D980-F,D988,E100, E108 E200, E200-B, E200-E, E208, E208-B, E230-L E250, E250-D, E250-i, E250-L, E251, E251-L E251-C, E2510, E256, E258, E258D, E260,E330 E330-N, E335, E338, E340, E340-E, E348, E350 E350-E, E358, E360, E368, E370, E370L, E376 E378, E380, E388, E390, E398, E420, E428 E480, E488, E500, E590, E598, E630, E635 E638, E640, E648, E700, E708, E730, E736 E738, E740, E746, E747, E750, E758, E760 E768, E780, E786, E788, E800, E800-N E808, E820, E830, E838, 848-I, E1050-CHN E1050V, E1070, E1070-C, E1070M, E1070T E1075, E1075L, E1080, E1080-C, E1080i E1080-T, E1085, E1085-L, E1085T, E1086 E1086i, E1086L, E1088-C, E1100, E1100-C E1100-T, E1101-C, E1105-T, E1107, E1107-DX E1107L,E1110,E1110-C, E1113-C, E1117, E1117L E1117,E1120, E1120-C, E1125, E1125W, E1125-SEA E1130, E1130B, E1150-MEA-SEA, E1150-CHN, E1153 E1155L, E1160, E1160-DX, E1170, E1180, E1182 E1182L, E1190, E1210, E1210M, E1210S, E1220 E1220i, E1252, E1310B, E1310-C, E1310-E, E1310M E1310S, E1360B, E1360, E1360-C, E1360-S, E1360-M E2100, E2100-B, E2100-C, E2120, E2120i, E2120L E2121B, E2152, E2210, E2210-B, E2210-C, E2210T E2370, E2550, E2550D, E2558, E3510S, S3510U F110, F118, F250, F250-L, F258, F265-LF268 F270, F270-L, F275-L, F278, F278i,F480L, F488E G600, G600G, G608, G618, G808E,J150, J150B,J210 J218, J700, J700i, J700L, J706, J708, J708i J770, J800, J800R, J808, J808E,L258, L310 L600, L608, L700, L708, L708E,M110, M130L M140, M140L, M150, M158, M200, M2310, M2710 M2710-C, M2710-L, M3200, M3510, M3510-C,M610 M618,P180, P200, P220, P250, P260, P270, P850 P858,P906,S366, S500, S508, S3100, S3100, S3110 S3110-C, S3370E, S3600, S3600-C, S3600i, S3601C S5050, S5200, S5200-C, S5550, S5550U,T139, T219 T309, T239, T509, T429, T729, T809,U708E, U800E U808E, U900L, U908E,X100, X108, X460, X468, X490 X495, X497, X540, X550, X560, X560L, X566, X576 X600, X608, X620, X628, X640, X648, X650, X656 X658, X670, X678, X700, X700N, X708,...(all new)

É 2012 www.gsm-support.eu